



Healthy Canadians

Home > Recalls & alerts



3M SafeLight Safety Harness 10910

Report a Concern

Starting date:

August 16, 2013

Posting date:

August 16, 2013

Type of communication:

Consumer Product Recall

Subcategory:

Miscellaneous Health Canada

Source of recall: Issue:

Product Safety, Physical Hazard

Audience:

General Public

Identification number:

RA-35015

Affected products

What you should do

Affected products

3M SafeLight Safety Harness 10910

Product description

The affected product is a full body safety harness. The harness has yellow and black 4.5 centimetre (1 $^{3/4}$ inch) webbing with pass through mating connector buckles at the leg and chest straps. There is a black and white laminated product label with 3M brand mark and manufacturer information.

The following products are affected by the recall:

Safety harnesses affected by this recall:

Model	Date codes	UPC	Batch Number
10910	May 1, 2012 to August 31, 2012	78371000790	WO30502770
			WO30510681
			WO30511698
			WO30519806

13/08/19

Hazard identified

Internal testing by 3M has indicated that the product did not meet the independent harness strength test as required in the Canadian Standards Association standard, which may pose a fall hazard to the user.

Neither Health Canada nor 3M has received any reports of incidents or injuries to Canadians related to the use of this safety harness.

Number sold

An unknown number of the safety harnesses were sold into Canada.

Time period sold

The recalled safety harnesses were sold from May 2012 to July 2013.

Place of origin

Manufactured in the United States of America.

Companies

Distributor

3M

Maplewood Minnesota

UNITED STATES

Images (select thumbnail to enlarge)



What you should do

Consumers should stop using the recalled harness immediately and contact their 3M distributor or 3M for verification and replacement of product.

For more information, consumers can contact 3M Technical Service Support directly: Ray Mann by telephone at 1-704-743-2406 or by email, or Michael Cameron by telephone at 1-704-743-2405 or by email.

Please note that the *Canada Consumer Product Safety Act* prohibits recalled products from being redistributed, sold or even given away in Canada.

3M SafeLight Safety Harness 10910 - Recalls & alerts - Healthy Canadian... Page 3 of 3

Health Canada would like to remind Canadians to report any health or safety incidents related to the use of this product or any other consumer product or cosmetic by filling out the Consumer Product Incident Report Form.

Date modified: 2013-08-16



PRODUCT RECALL

3MTM Model 10910 SafeLight Full Body Harness with W/O Numbers 30502770, 30510681, 30511698 or 30519806



Dear 3M Customer:

Aug 19, 2013

In an effort to ensure that 3M provides our customers with high quality products and services, we have recently completed an analysis of Model Number 10910 SafeLight Full Body Harness (3M Material Number 70071532652) (UPC 78371000790). We have identified a limited number of these units manufactured from May to August, 2012 that may not meet the independent harness strength test when tested as defined by CSA Z259.10 requirements.

As a result, 3M has chosen to voluntarily recall the products which may have been impacted by this issue and requests that you immediately identify and remove from service all affected model 10910 SafeLight harnesses within your inventory. Affected products will be identified on the product label by W/O Number 30502770, 30510681, 30511698 or 30519806. W/O numbers other than those indicated in this notice are not affected by this recall notice. To locate the affected W/O number, please see sample label below with arrow pointing to location.

3M

3 M Occupational Health & Environmental Safety Division Concord, NC 28027 1-800-243-4630 www.JM.com/FallProtection

n MODEL\Mod'ele:

10910 SafeLight Harness Size/Grandeur Universal WO30502770 70071532652

eets OSHA REGULATIONS ANSI Z359.1-07 CSA Z259.10-06



Capacity Capacite: 310 lb (141 kg)

Do Not Remove Tag / Ne Pas Enlever

Webbing/Sangle / Polyester

Hardware/Pie ce de Metal / Stee/Acier

Made in USA with Globally Sourced Materials

We request that the following steps be implemented by your company:

- Immediately identify and remove from service all affected inventory of model 10910 SafeLight harnesses identified by W/O Numbers 30502770, 30510681, 30511698 or 30519806.
- Contact Ray Mann at 3M by calling 704-743-2406 or via e-mail at ray.mann@mmm.com, or Michael Cameron by calling 704-743-2405 or via e-mail at michael.cameron@mmm.com with W/O number to arrange for further instructions and shipment of replacement product.

3M remains committed to providing high quality products and services to our customers. We sincerely apologize for any inconvenience that this situation may cause you or your customers.

Thank you for your continued support and use of 3M products and services.

Best regards,

Jack Cardwell U.S. Sales and Marketing Director Robert Weber Global Quality and Regulatory Manager

How D. Weber